

North Shoreline – Beach Nourishment at Remaining Wall



North Shoreline – Completed Beach Prior to Revegetation



North Shoreline – Riparian Re-vegetation



North Shoreline – Relocated Lawn and New Picnic Area




North Shoreline Restored Beach



Phase 1: Other Biological Monitoring




Forage Fish Monitoring



Eelgrass Monitoring

Phase 2: North Shoreline Monitoring

- Pre-Construction:
 - Eelgrass
 - Physical Beach Sediment
 - Forage Fish
- Post-construction:
(To Be Completed)



4. Summary and Conclusions

- Is It Working?
- Upcoming Presentations and Site Walks



Is It Working?

Coastal and Bluff Geology



Is It Working?

Nearshore Habitat Diversity and Connectivity



Is It Working?

Integrating Habitat and Recreation



Upcoming Presentations and Site Walks

- **Hillside Geology Guided Tour**
Saturday, Oct. 4, 10:00 am
by Bill Laprade







Thank
You!

**Contact
Information:**

John Small
jsmall@anchoragea.com
(206) 287-9130

Phase 2 Project



Pacific Madrone



Pacific Madrone



Salal




Douglas Fir



Western Hemlock



Western Red Cedar



Snowberry



Red Twig Dogwood



Nootka Rose



Salmon Berry



Red Alder



Big Leaf Maple



Indian Plum (seral)



Red Flowering Currant



Thimble Berry



Sword Fern

